

SEWING MACHINE TABLE
COMFORT NEXT
СТОЛ ДЛЯ ШВЕЙНОЙ МАШИНЫ



SYMBOLS



ATTENTION

ВНИМАНИЕ




ASSEMBLY & ADJUSTMENT

СБОРКА РЕГУЛИРОВКА




OPERATION

ЭКСПЛУАТАЦИЯ



INDICATING MARK













ОБОЗНАЧЕНИЕ



























EVEN SURFACE


РОВНАЯ ПОВЕРХНОСТЬ

010001	1 X	010003	1 X	010004	1 X
010006	1 X	010007	1 X	010013	1 X
010015	1 X	010023	1 X	010024	1 X
010025	1 X	010026	1 X	010027	1 X
010032	1 X	010038	1 X	010039	1 X
010040	1 X	010043	1 X		

 020001 2x 020002 2x		 020004 2x 020005 2x		 020006 2x	 020011 1x	 020012 1x	 020018 4x
 020013 CR 2x		 020013 CL 2x		 020016 2x		 020021 4x	
 020015 DL 2x		 020015 DR 2x					

 030001 12x 3 * 16	 030002 36x 3,5 * 16	 030003 18x 6,2 * 50	 030033 2x 4,2 * 13	 030006 6x 2,9 * 13	 030008 4x φ 4	 030004 4x φ 5 * 16
 030009 4x M4 * 20	 030011 18x φ 15	 030012 12x φ 18	 030013 12x L 35	 030014 12x φ 15 h 12		 030028 8x 3,9 * 16
 030015 2x φ 8 * 30	 030016 2x φ 8 * 30	 030017 2x φ 15 h 10	 030022 4x M 10	 030023 4x φ 10	 030031 4x φ 10 s2,5	

<p>1x 050002</p> 	<p>1x 050004</p> 	<p>1x 050005</p> 
<p>1x 050003</p> 		
<p>S4 1x</p> 		



010001

010004

5

6x  030014

6x  030012










010003

010006



*
Входит в комплект стола.
Included into table set.





*
Входит в комплект стола.
Included into table set.

